


| DIMENSIONES EN mm. | |
|--------------------|-----|
| L | H |
| 594 | 594 |
| 420 | 420 |
| 297 | 297 |
| 210 | 210 |
| 148 | 148 |
| 105 | 105 |



OB - 1



OB - 2




OB - 3



OB - 4



OB - 5




OB - 6



OB - 7



OB - 8



OB - 9




OB - 10



OB - 11



OB - 12



OB - 13



OB - 14



OB - 15



OB - 16



OB - 17




OB - 18



OB - 19



OB - 20



OB - 21



OB - 22



OB - 23



OB - 24



OB - 25



OB - 26




OB - 27



OB - 28



OB - 29



OB - 30



OB - 31



OB - 32



OB - 33




OB - 34



OB - 35



OB - 36



| DIMENSIONES EN mm. | | |
|--------------------|-----|-----|
| H | L | D |
| 1000 | 650 | 594 |
| 600 | 450 | 420 |
| 500 | 330 | 297 |
| 330 | 230 | 210 |
| 250 | 170 | 148 |
| 180 | 125 | 105 |



OBR - 41



OBR - 42



OBR - 43



OBR - 44



OBR - 45



OBR - 46



OBR - 47



OBR - 48



OBR - 49



OBR - 50



OBR - 51



OBR - 52



OBR - 53



OBR - 54



OBR - 55



OBR - 56



OBR - 57



OBR - 58



OBR - 59



OBR - 60



OBR - 61



OBR - 62



OBR - 63



OBR - 64



OBR - 65



OBR - 66



OBR - 67



OBR - 68



OBR - 69



OBR - 70



OBR - 71



OBR - 72



OBR - 73



OBR - 74



OBR - 75



OBR - 76



OBR - 77



OBR - 78



OBR - 79



OBR - 80




OBR - 81




OBR - 82



OBR - 83



OBR - 84



OBR - 85